

2 PEOPLE PER GAP MAXIMUM

NO ADMITTANCE EXCEPT:

MECHANICAL	SMT	OTHER
Jim Fagan Pete Simon Rolando Flores Bob Kubinski Russ Rucinski	Breese Quinn Eric Kajfasz Ron Lipton Petros Rapidis	Lynn Bagby Reidar Hahn John Foglesong Marvin Johnson John Anderson Abid Patwa

ALL OTHERS NEED PRIOR APPROVAL FROM DMITRI DENISOV.

KEEP GATES LOCKED WHEN NOT OCCUPIED

VIOLATORS WILL BE SUBJECT TO DISCIPLINARY ACTION.

1/12/2003

Gap Rules for Authorized Persons

1. There is extremely delicate equipment in the gaps, including beam pipe. Any damage to the equipment will harm the whole D0 Collaboration extremely badly. All your operations in the gaps should with highest priority lead to NO damage to existing installations. We have enough time to finish all work planned in a timely fashion - do not rush, please.
2. Only people authorized to work in the gaps are allowed in that space, no exceptions.
3. Do only job which has to be done in the gaps. Any testing, etc. which could be done outside of the gaps area should be done elsewhere.
4. Bring only minimal number of tools/equipment with you, remove EVERYTHING, including removed detectors/electronics parts from the gaps after you are done. Do not wear a hard hat in the gap.
5. When you leave the gap you have to lock the door(s). Do not assume that somebody will work after you.
6. Not more then 2 people are allowed at the same time in any gap.
7. If you need help - find person to work with you. Russ will organize techs help with highest priority for gaps work.
8. You should follow all safety rules outlined in D0 Hazard awareness, Radiation Worker and LOTO.
9. Do not let unauthorized people in gap. Do not publicize Lock combination.
10. In the case any damage is done/suspected or you see any problematic areas, inform Run Coordinator (phone, pager) immediately.